**proline**
decorative concrete systems

Keep it random
Overlap tools 6 in to 8 in

*Note: Use the tool name on the back of tool to reference the orientation

*Tips: A good idea is to stamp some of the tools at angles to create a more random effect. This method is most effective with textures that have veins going through them

*Tips: Never pick up a tool and then put it down in the same place, same orientation as before, it will create a ghost image of the pattern

Reverse lap method

*Tips: When checking impression make sure to stand on the tool so that the tool does not move at all

1

Seam line from previous spot

Repeat

2

Area of mat to tamp, keep away from edges. Reverse lap to avoid imprinting edge of tool

*Note: Do not stamp up to edge to avoid seam line. A good method to get rid of seam lines from the previous spot is to stamp next tool overlapping the previous spot by reverse lapping them

prolinestamps.com
TEL: 1-800-795-4750 Toll free